
M712306

FRACTOGRAPHIC ANALYSES OF DENSIFIED CERAMICS AND GLASS-CERAMICS BALLISTICALLY IMPACTED BY CALIBER . 30 M2 PROJECTILES

WILLIAM D. LONG and WILLIAM A. BRANTLEY CERAMICS DIVISION


July 1970



This document has been approved for public release and sale; its distribution is unlimited.

ARMY MATERIALS AND MECHANICS RESEARCH CENTER Watertown, Massachusetts 02172

Reproduced by the CLEARINGHOUSE for Federal Scientific & Technical Information Springfield Va. 22151



The findings in this report are not to be construed as an official Department of the Army position, unless so designated by other authorized documents.

Mention of any trade names or manufacturers in this report shall not be construed as advertising nor as an official indorsement or approval of such products or companies by the United States Government.

DISPOSITION INSTRUCTIONS

Destroy this report when it is no longer needed.

Do not return it to the originator.

AMMRC TR 70-17

FRACTOGRAPHIC ANALYSES OF DENSIFIED CERAMICS AND GLASS-CERAMICS BALLISTICALLY IMPACTED BY CALIBER .30 M2 PROJECTILES

Technical Report by

WILLIAM D. LONG, 1LT, Ord C, and WILLIAM A. BRANTLEY, CAPT, Ord C

July 1970

D/A Project 1T062105A330 AMCMS Code 502E.11.296 Ceramic Materials Research for Army Materiel Agency Accession Number DA OB4802

This document has been approved for public release and sale; its distribution is unlimited.

CERAMICS DIVISION
ARMY MATERIALS AND MECHANICS RESEARCH CENTER
Watertown, Massachusetts 02172

ARMY MATERIALS AND MECHANICS RESEARCH CENTER

FRACTOGRAPHIC ANALYSES OF DENSIFIED CERAMICS AND GLASS-CERAMICS BALLISTICALLY IMPACTED BY CALIBER .30 M2 PROJECTILES

ABSTRACT

Utilizing low magnifications, fractographic analyses have been conducted on low-temperature densified ceramics and glass-ceramics ballistically impacted by caliber .30 M2 projectiles. From examinations of fracture-exposed surfaces, the macroscopic sequence of ballistic fracture occurring outside the initial conoid has been determined and found to be qualitatively similar for both material classes and for impact by both BALL and AP projectiles. Observations indicate that a number of imperfections such as irregularities in as-received specimen surfaces and internal macroporosity induce alterations in ballistic crack fronts.

CONTENTS

	rage
ABSTRACT	
INTRODUCTION	1
EXPERIMENTAL	1
RESULTS AND DISCUSSION	1
CONCLUSIONS	3
RECOMMENDATIONS	3
ACKNOWLEDGMENTS	3
LITERATURE CITED	4
FIGURE 1. FRACTURE PATTERNS OF GLASS-CERAMICS FOLLOWING BALLISTIC	
IMPACT BY CALIBER .30 M2 PROJECTILES	5
FIGURE 2. FRACTURE PATTERNS OF DENSIFIED CERAMICS FOLLOWING BALLISTIC IMPACT BY CALIBER .30 M2 PROJECTILES	10

INTRODUCTION

Utilizing computer codes, the macroscopic fracture sequence of ceramic composite armor impacted by ogive-shaped, hardened steel, small arms projectiles has been recently predicted. Principal features of this fracture sequence, which typically is completed within less than 50 microseconds after impact, have been confirmed by employing high-speed cameras with flash X-ray^{1,2} and optical techniques. In addition, Fréchette and Cline have employed fractographic analyses at a variety of magnifications, ranging from visual observation to electron microscopy, to confirm the macroscopic fracture sequence and elucidate elements of the microscopic deformation and fracture behavior of ceramics. It is noteworthy that the detailed macroscopic fracture sequence reported by Fréchette and Cline is qualitatively similar for a wide variety of materials, such as steels, single-crystal and polycrystalline aluminas, beryllium oxide, boron carbide, and glasses, impacted by both ogive-shaped and blunt projectiles.

The purpose of the present investigation is to analyze the fracture surfaces of relatively inexpensive and easily fabricated candidate ceramic armor materials following ballistic impact by caliber .30 M2 projectiles in order to determine the macroscopic sequence of fracture and the possible effects of ceramic macrostructure on the ballistic fracture response. Materials employed in this investigation comprise two classes: (1) Cer-Vit glass-ceramic compositions, C-101, C-117, and C-126, obtained from Owens-Illinois Development Center, Toledo, Ohio; and (2) impregnated and low-temperature densified alumina, silicon carbide, and silicon carbide-silicon nitride ceramics obtained from Kaman Nuclear, Colorado Springs, Colorado.* Ballistic results obtained for these materials form the subject of a separate report (AMMRC TR 70-19).

EXPERIMENTAL

Glass-ceramic ballistic specimens, approximately 1/3-inch thick by 6 inches in diameter, and densified ceramic ballistic specimens, approximately 1/3-inch thick by 6 inches square with rounded corners, were individually mounted on 12" x 12" x 1/4" Doron plates. These composite armor specimens were tested by impact with caliber .30 BALL M2 and AP M2 projectiles at the AMMRC ballistic range, utilizing testing techniques specified elsewhere. Subsequent to ballistic impact, individual specimens were observed under low magnifications, below 5X, in order to determine the macroscopic fracture sequences and to examine topographical features of particular interest. Macrophotographs taken of typical fracture patterns and fracture pattern anomalies are displayed and discussed in the following section.

RESULTS AND DISCUSSION

Macroscopic fracture patterns and general fracture sequences (Figures 1 and 2) for both material classes are qualitatively similar to those reported by Fréchette and Cline. 4 In the present study, several different methods to retain

^{*}Compositional and processing details for these materials are proprietary.

intact portions of the ceramics nearest the ballistic impacts were unsuccessful; hence, elements of the initial sequences within the fracture conoids could not be determined. These methods included using a styrofoam-lined box containing an approximately 1-1/2-inch-diameter central hole through which both V_{50} -range and low-velocity projectiles were shot and utilization of several layers of masking tape to hold fragments in place.

Even though portions from fracture conoids could not be employed to reconstruct the initial fracture sequences, it is obvious that ballistic energy absorption is greatest near the axis of impact. In all cases, fragments become larger in size on proceeding radially from the impact axis to the periphery of the impacted specimens.

Initial radial cracks having included angles between 30° and 45° occur prior to circumferential cracks. This sequence is particularly evident in Figures 1b and 2d and is determined from the discontinuity of circumferential cracks at intersections with radial cracks. However, subsequent radial cracks are also initiated after circumferential cracking has commenced. This behavior is inferred from the continuity of circumferential cracks at intersections with radial cracks and may be observed in Figures 1c and 2a. Late-time front face spallation is frequently observed to occur toward the periphery (Figures 1a, 1c, 2d, and 2e) and is generally initiated at the intersection of radial and circumferential cracks. The peripheral fracture domain size and distribution is indicative of the relative amounts of ballistic energy absorbed by the ceramic for varying projectile velocities as depicted in Figures 1a, 1b, 2d, and 2e where projectile velocities were greater for Figures 1b and 2d.

Particularly evident, moreover, is the corrugated nature of many fracture-exposed surfaces which for a given specimen lie on several planes approximately perpendicular to the impact axis (Figures 1b and 2a). It is reasonable to correlate qualitatively the distance between such parallel fracture planes with both the axial stress generated by projectile impact and the dynamic tensile strength of the target ceramic. The corrugated topography of the fracture surface is postulated to arise from modulation of the local axial stress by the radial and circumferential stress components, with the corrugation wavelength indicative of stress wave reverberations. The corrugations are less prominent for the densified ceramics than for the glass-ceramics. It is thought that the greater porosity present in the former materials, resulting in greater stress wave attenuation and perhaps finer scale fracture, might be responsible.

Macroscopic irregularities in the surface topography of the as-received densified ceramic specimens are observed to have a profound influence on crack propagation. Both forming features (Figure 2c) and scribed identification marks (Figures 2a, 2b, and 2e) induce preferential crack propagation. Furthermore, as depicted in Figure 2a, internal macroporosity afters the direction of the fracture path within the densified ceramic. It is evident that the fracture path has changed direction in order to intersect each pore near its center. This result would suggest that porosity, acting as regions of stress concentration, might degrade ballistic performance by enhancing ceramic fracture during ballistic impact. Edge effects due to specimen geometry are also evident for the densified ceramics. Initial radial cracks in square tiles seek out the tile corners (Figure 2e) rather than spreading randomly from the center of impact.

However, the relative importance of edge effects occurring outside the fracture conoid for degrading ballistic performance is not known at present.

CONCLUSIONS

- 1. Following ballistic impact, initial radial cracks having 30° to 45° included angles precede circumferential cracks in the ceramics that were investigated. Secondary radial cracks having smaller (5° to 10°) included angles are initiated subsequent to circumferential cracking.
- 2. The ballistic fracture path frequently follows topographical irregularities in the front surface of the ceramic face plate.
- 3. Internal macroporosity, and possibly other internal defects, induces a local alteration of the fracture path. For the macroporosity observed in the present study, the fracture path is induced to intersect the pores.
- 4. Ceramic tiles for ballistic evaluation that are either 6 inches in diameter or 6 inches square insufficiently wide to eliminate edge effects during ballistic fracture, particularly when ballistic impacts are off-center.

RECOMMENDATIONS

Based upon observations during the present investigation, a number of recommendations are suggested for continuing research in this area:


- 1. Further fractographic analyses of these materials on a microscale are suggested. Some points of interest are possible correlation of the relative amount of total ballistic energy absorption with microtopography for each portion of the fracture sequence, study of the effects of increasing the percentage of crystalline phase in glass-ceramics on fracture behavior, examination of densified ceramics for preferential ballistic fracture at the matrix-impregnant interface, and study of fracture-exposed surfaces near porosity to determine whether porosity inhibits, increases, or does not alter the velocity of the crack front.
- 2. Improvements in the materials utilized for ballistic testing are desirable. Ceramic tiles for ballistic testing should have surfaces as free of irregularities as possible, and ballistic testing of new and existing materials should be performed, whenever possible, with circular tiles having a minimum diameter of at least 8 inches in order to minimize edge effects during fracture following off-center impact. Further study is necessary to assess the importance of edge effects in degrading ballistic performance.

ACKNOWLEDGMENTS

The authors wish to express their appreciation to S. Nanfria and other personnel of the AMMRC photographic laboratory for the excellent photographs of fracture-exposed surfaces displayed in this report. The authors are particularly grateful to Professor V. D. Fréchette of Alfred University who kindly provided a copy of his presentation cited in Reference 4.

LITERATURE CITED


- 1. WILKINS, M. L. Third Progress Report of Light Armor Program (U). Lawrence Radiation Laboratory, University of California, Livermore, California, Report No. UCRL 50460, July 1968.
- 2. FLORENCE, A. Interaction of Projectiles and Composite Armor Part II (U). Stanford Research Institute, Contract DAAG46-68-C-0054, Final Report AMMRC CR 69-15, August 1969.
- 3. TAYLOR, J. W. Dual-Hardness Armor (U). Confidential Paper from Defense Ceramics Information Center, Columbus, Ohio, DCIC Report No. 69-1, Part II, May 1969.
- 4. FRÉCHETTE, V. D., and CLINE, C. F. Fractography of Ballistic Tested Ceramics. Presented at the Annual Meeting of the American Ceramic Society, Washington, D. C., May 1969.
- 5. MASCIANICA, F. A. Summary of Terminal Ballistic Data on Lightweight Armor Materials (U). Confidential Report, Army Materials and Mechanics Research Center, Watertown, Massachusetts, AMMRC TR 69-17, July 1969.



C101 (AP) Mag. 1X

Figure 1a. FRACTURE PATTERNS OF GLASS-CERAMICS FOLLOWING BALLISTIC IMPACT BY CALIBER .30 M2 PROJECTILES


19-066-268/AMC-70



C101 (BALL) Mag. 2X

Figure 1b. FRACTURE PATTERNS OF GLASS-CERAMICS FOLLOWING BALLISTIC IMPACT
BY CALIBER .30 M2 PROJECTILES

19-066-271/AMC-70



C117 (BALL) Mag. 1X

Figure 1c. FRACTURE PATTERNS OF GLASS-CERAMICS FOLLOWING BALLISTIC IMPACT
BY CALIBER .30 M2 PROJECTILES

19-066-264/AMC-70




Figure 1d. FRACTURE PATTERNS OF GLASS-CERAMICS FOLLOWING BALLISTIC IMPACT
BY CALIBER .30 M2 PROJECTILES




Figure 1e. FRACTURE PATTERNS OF GLASS-CERAMICS FOLLOWING BALLISTIC IMPACT
19-066-269/AMC-70

BY CALIBER .30 M2 PROJECTILES



Interaction between porosity and crack front in densified silicon carbide. (BALL)
Figure 2a. FRACTURE PATTERNS OF DENSIFIED CERAMICS FOLLOWING BALLISTIC
IMPACT BY CALIBER .30 M2 PROJECTILES

19-066-270/AMC-70




18,546 5 2 3

Fracture through surface imperfection in densified silicon carbide. (BALL)

Figure 2b. FRACTURE PATTERNS OF DENSIFIED CERAMICS FOLLOWING BALLISTIC

IMPACT BY CALIBER .30 M2 PROJECTILES

19-066-263/AMC-70



Fracture through surface imperfection in densified aluminum oxide (BALL)

Figure 2c. FRACTURE PATTERNS OF DENSIFIED CERAMICS FOLLOWING BALLISTIC


IMPACT BY CALIBER .30 M2 PROJECTILES

19-066-266/AMC-70



Rearmost portion of fracture conoid for densified silicon carbide - silicon nitride. (BALL)
Figure 2d. FRACTURE PATTERNS OF DENSIFIED CERAMICS FOLLOWING BALLISTIC
IMPACT BY CALIBER .30 M2 PROJECTILES

19-066-262/AMC-70



Prominent front-face spallation in fracture for densified silicon carbide - silicon nitride (AP)
Figure 2e. FRACTURE PATTERNS OF DENSIFIED CERAMICS FOLLOWING BALLISTIC
IMPACT BY CALIBER .30 M2 PROJECTILES

19-066-261/AMC-70

UNCLASSIFIED

Security Classification						
	CONTROL DATA - R &					
(Security classification of title, body of abstract and inc 1 ORIGINATING ACTIVITY (Corporate author)			ell report is classified)			
Army Materials and Mechanics Research C	Center	Unclassified				
Watertown, Massachusetts 02172	28	26. GROUP				
3. REPORT TITLE						
FRACTOGRAPHIC ANALYSES OF DENSIFIED CER		ERAMICS				
BALLISTICALLY IMPACTED BY CALIBER .30 M	12 PROJECTILES					
4. DESCRIPTIVE NOTES (Type of report and inclusive dates)						
5. AUTHOR(S) (First name, middle initial, last name)	· · · · · · · · · · · · · · · · · · ·					
William D. Long and William A. Brantley	•					
6. REPORT DATE	78. TOTAL NO. OF P	AGES 7b.	NO. OF REFS			
JULY 1970 Se. CONTRACT OR GRANT NO.	17		<u> </u>			
MA. CONTRACT OR GRANT NO.	SA. ORIGINATOR'S R	EPORT NUMBER	5)			
b. PROJECT NO. D/A 1T062105A330	AMMRC TR 70-	17				
c.AMCMS Code 502E.11.296	96. OTHER REPORT	9b. OTHER REPORT NO(8) (Any other numbers that may be assigned				
₄Agency Accession Number DA OB4802						
10. DISTRIBUTION STATEMENT						
This document has been approved for pub is unlimited.	olic release and sa	ile; its dis	stribution			
11. SUPPLEMENTARY MATES	Tra sponsoping MIL	12.454.457.11154	· · · · · · · · · · · · · · · · · · ·			

Utilizing low magnifications, fractographic analyses have been conducted on low-temperature densified ceramics and glass-ceramics ballistically impacted by caliber .30 M2 projectiles. From examinations of fracture-exposed surfaces, the macroscopic sequence of ballistic fracture occurring outside the initial conoid has been determined and found to be qualitatively similar for both material classes and for impact by both BALL and AP projectiles. Observations indicate that a number of imperfections such as irregularities in as-received specimen surfaces and internal macroporosity induce alterations in ballistic crack fronts. (Authors)

U. S. Army Materiel Command Washington, D. C. 20315

Ē	PORM	1473	REPLAC	TE FOR ARI	4 1478. 47 UBE.	1 JAN 64.	WHICH IS

UNCLASSIFIED
Security Classification

14 KEY WORDS		LINK A		LINK B		LINK C	
		WT	ROLE	WT	ROLE	WT	
Fractography			,		1		
Ceramics			1				
Glass ceramics			l				
Terminal ballistics				l			
Armor							
Lightweight armor Devitrified glass		ł		ľ			
Devitrified glass		l			ļ		
		ļ					
		Ì			İ .		
-							
				ĺ		ł	
			1				
					[
				}	<u> </u>		
	l .						
)						
					j		
]					
						ł	
	ł					ł	
	Ì						
]					

UNCLASSIFIED
Security Classification